



TB0060 Change of Part Number for Sensor Plugs

Date: 8 Oct 07	Author: Richard Brown	TB0060	Cross Ref: SL0015 V2
----------------	-----------------------	--------	----------------------

Part EL-34171 has been replaced by part EL-37699, Sensor Inclinometer VTI 2-Axis M12 Plug (see photo below)

They are the same part, the only difference being that in EL-37699, the plug has been injected with a resin compound designed to protect it from moisture. This issue is referenced in SL0015 V2.

The new part is completely backwardly compatible with the old part as this is the only difference. However please note that we are no longer providing EL-31471 as a spare part, only EL-37699.



EL-31471, now known as EL-37699