

TB0009 SB360 & SB300/330 Timer Delay Relay as Fitted to Power Pack Machines

Date: 16/03/99

As from Machine Serial number SB6593 for SB30 /33 units and SB6600 for MK6 units this relay has been superseded by a non adjustable relay and capacitor. This will give the three second delay the original timer was set to.