

## **TB0039 Replacement of L-pin on SB361/SB401**

Date: 9 November 2005

The L-pin on SB361/SB401 has been changed from the square head type which is retained by a circlip, to retaining screw type. The first new L-pins appeared on the SB7652 (E-20). The pins are not completely interchangeable as a minor mod has to be carried out on the stabilizer housing, S8-33181.

### **Models affected:**

All 361s & 401s

### **BOM:**

All boms updated

### **Spare Parts:**

New L-pin: PN-35349 replaces PN-33266