

TB0041 Drainage holes on SB121 High Crane Base

Date: 28 Nov 2005

Description:

We have added two dia 16mm holes to the drawing S2-32493 (now rev C) to overcome reported problem of rainwater build-up inside the high crane base.

Models and Markets:

All SB121s in all markets

Backward Compatibility:

Holes can be added by service agents per our instructions

References:

See red circled areas in drawing.

