



## TB0064 Camber and Elevation Change in SMARTlift settings

Date: 24 Jan 08	Author: Richard Brown	Distribution: ALL
-----------------	-----------------------	-------------------

Camber and Elevation limits were changed from Sidelifter SB7850 onwards. Units prior to SB7850 that have had a software upgrade to 3.22 or above will also be affected. (Go to MAIN MENU - VIEW OPERATING HOURS - The software version is in the top right hand corner.)

This information is also in the Operators Manual provided with all units.

### **Camber Limit**

Prior to SB7850 = +/- 10deg

After SB7850 = +/-6deg

### **Elevation Limit**

Prior to SB7850 = +/- 6deg

After SB7850 = +/-4deg

### **Impact of change**

If the camber/elevation limits are exceeded, a warning screen will display. The current value will display at any time in the Sensor Values Menu.