



## TB0069 Non-fitment of Container Joiner Poles

Date: 17 December 2008	Author: Neil Savage	TB0069	
------------------------	---------------------	--------	--

### Description:

As of the 1 July 2009 no sidelifters will be fitted with the container joiner poles as standard. They will need to be ordered as an optional extra.

### Models and Markets:

All models & markets

### BOM:

There are 2 kits which call up the container joiner poles and associated brackets, if required:

LF-20122 (flange mounted)

LF-33967 (web mounted)

### Backward Compatibility:

N/A

### Use Instructions:

N/A

### Benefits and Advantages to Change:

Cost and weight saving

### References:

EC1174