



## **K0001 Correct Mix for Anti-Freeze**

K0001	Version 1	Power Pack	28 Jul 06
-------	-----------	------------	-----------

Affects all models with a Power Pack.

It is essential that the anti freeze mixture is checked, using a hydrometer, as part of the service schedule.

The correct mix is 50% water and 50% anti freeze.

Failure to comply with the recommended mixture can lead to serious component damage.