



## Air Spring Replacement Hendrickson HT230 Suspensions

### Category

Suspension

### Models and Markets

All model fitted with Hendrickson HT230 Suspension

### Information

When replacing the Air Spring on a HT230 Suspension (Hendrickson Part No S-21208) Ensure that the Goodyear Air spring IR13-119 is supplied which is a superior design to the Firestone W01455-8834 Air Spring.