

## **TB0022 SB360/330 Side Wear Pad Change**

Date: 06/11/01

As from serial number **SB6869** STEELBRO SB360 / SB330 side wear pads have changed in design.

The mounting holes have changed position however the pad has holes drilled for the old hole positions making the pad interchangeable.

This modification is the same for the 36mm and 10mm Side Wear Pad.

Size	Old part number	New part number	Drawing number
36mm	S1-20829	36mm S1-31066	Same
10mm	S6-18725	10mm S1-31067	Same