

# TB0059 New Bellhousing & Coupling Arrangement for Standard Power Pack

|--|

The standard powerpack on the Steelbro sidelifter has been changed to incorporate a new bellhousing and pump coupling arrangement.

### **Models and Markets:**

All sidelifters with powerpacks in all markets affected.

#### Parts:

Kit HC-37078 replaces the following items: S1-18306, S1-18307, S1-18482, HC-18793.


4x S1-37549 also required for securing electrical cables around edge of bellhousing.

# **Backward Compatibility:**

The entire old coupling arrangement can be replaced by the new set up. Details on how to do this are in Service Info K0005.


## **Benefits and Advantages to Change:**

New bellhousing is self-locating onto the engine body which will reduce the possibility of issues with coupling caused by misalignment, and simplifies assembly/service.



\*These three items make up kit HC-18793

Previous style



HC-37092 Gear Pump Coupling

All items marked make up new kit HC-37078

**TECHNICAL BULLETIN**