



# Hendrickson HT230TA17-521 Parts List



Taken from Hendrickson Parts List L38 Rev A July 1999 Printed in USA.  
File: T:\Template\OEMLIB\Hendrickson\HT230TA15-521 parts list.dwg

| 17   | C-20014-2 | Air Spring/Shock Mount Right | 1.00 |      |       |
|------|-----------|------------------------------|------|------|-------|
| 16   | C-20014-1 | Air Spring/Shock Mount Left  | 1.00 |      |       |
| 15   | S-20033/2 | Air Spring Bolt Kit          | 2.00 |      |       |
| 14   | S-20010   | Air Spring                   | 2.00 |      |       |
| 13   | S-20002   | Shock Absorber               | 2.00 |      |       |
| 12   | S-20031/2 | Bolt Kit Shock Absorber      | 2.00 |      |       |
| 11   | D-21165-2 | Frame Bracket Right          | 1.00 |      |       |
| 10   | D-21165-1 | Frame Bracket Left           | 1.00 |      |       |
| 9    | S-24691   | Tri-Function Bush Kit        | 2.00 |      |       |
| 8    | S-20924   | Inside Washer                | 2.00 |      |       |
| 7    | S-20925   | Eccentric Washer             | 2.00 |      |       |
| 6    | S-24679   | Pivot Bolt Kit               | 2.00 |      |       |
| 5    | S-11613   | Wear Pad                     | 4.00 |      |       |
| 4    | S-20701   | Axle Spacer                  | 4.00 |      |       |
| 3    | S-20032/4 | U Bolt Kit                   | 4.00 |      |       |
| 2    | S-20000-2 | Beam Assembly Right          | 1.00 |      |       |
| 1    | S-20000-1 | Beam Assembly Left           | 1.00 |      |       |
| Item | Part No   | Description                  | Qty  | Unit | Notes |

# Hendrickson HT230TA15-522 Parts List




Taken from Hendrickson Parts List L38 Rev A July 1999 Printed in USA.

Except Item13 taken from Part no 98873-013.

File: T:\Template\OEMLIB\Hendrickson\HT230TA15-522 parts list.dwg

| 17   | C-20012-1 | Air Spring/Shock Mount Right | 1.00 |      |       |
|------|-----------|------------------------------|------|------|-------|
| 16   | C-20012-1 | Air Spring/Shock Mount Left  | 1.00 |      |       |
| 15   | S-20033/2 | Air Spring Bolt Kit          | 2.00 |      |       |
| 14   | S-20010   | Air Spring                   | 2.00 |      |       |
| 13   | B-21699   | Shock Absorber               | 2.00 |      |       |
| 12   | S-20031/2 | Bolt Kit Shock Absorber      | 2.00 |      |       |
| 11   | D-21179-2 | Frame Bracket Right          | 1.00 |      |       |
| 10   | D-21179-1 | Frame Bracket Left           | 1.00 |      |       |
| 9    | S-24691   | Tri-Function Bush Kit        | 2.00 |      |       |
| 8    | S-20924   | Inside Washer                | 2.00 |      |       |
| 7    | S-20925   | Eccentric Washer             | 2.00 |      |       |
| 6    | S-24679   | Pivot Bolt Kit               | 2.00 |      |       |
| 5    | S-11613   | Wear Pad                     | 4.00 |      |       |
| 4    | S-20701   | Axle Spacer                  | 4.00 |      |       |
| 3    | S-20032/4 | U Bolt Kit                   | 4.00 |      |       |
| 2    | S-20000-2 | Beam Assembly Right          | 1.00 |      |       |
| 1    | S-20000-1 | Beam Assembly Left           | 1.00 |      |       |
| Item | Part No   | Description                  | Qty  | Unit | Notes |

# Hendrickson HT230TA15-523 Parts List




From HT230TA15-524 Steelbro.dwg

File:P:\OEMLIB\Hendrickson\Parts lists\HT230TA15-523 parts list.dwg

| 15   | 98947-001 | Spacer Airspring            | 2.00 |      | Only for 378-409 Ride height      |
|------|-----------|-----------------------------|------|------|-----------------------------------|
| 14   | S-22630   | Hardware Kit Airspring      | 2.00 |      | Only for 378-409 Ride height      |
| 13   | S-21251   | Air Spring Mounting Kit     | 1.00 |      | Only for 350-381 Ride height      |
| 12   | 98948-001 | Plate-Air Spring Mounting   | 2.00 |      |                                   |
| 11   | S-21208   | Air Spring                  | 2.00 |      |                                   |
| 10   | A-21140   | U-Bolt/Spacer Kit           | 1.00 |      |                                   |
| 9    | C-20023   | Upper Shock Clevis          | 2.00 |      | Can be mounted in either position |
| 8    | A-20031   | Shock Bolt Kit              | 1.00 |      | Can be mounted in either position |
| 7    | A-20002   | Shock absorber              | 2.00 |      | Can be mounted in either position |
| 6    | S-24691   | Tri-Function Bush Kit       | 2.00 |      |                                   |
| 5    | S-24680   | Pivot Bolt/Washer Kit, QA   | 2.00 |      |                                   |
| 4    | D-21179-2 | Frame Bracket assembly (RH) | 1.00 |      |                                   |
| 3    | D-21179-1 | Frame Bracket assembly (LH) | 1.00 |      |                                   |
| 2    | D-20000-2 | Beam Assembly (RH)          | 1.00 |      |                                   |
| 1    | D-20000-1 | Beam Assembly (LH)          | 1.00 |      |                                   |
| Item | Part No   | Description                 | Qty  | Unit | Notes                             |

# Hendrickson HT230TA15-524 Parts List



From HT230TA15-524 Steelbro.dwg

File:P:\OEMLIB\Hendrickson\Parts lists\HT230TA15-524 parts list.dwg

| 15   | 98947-001 | Spacer Airspring            | 2.00 |      | Only for 378-409 Ride height      |
|------|-----------|-----------------------------|------|------|-----------------------------------|
| 14   | S-22630   | Hardware Kit Airspring      | 2.00 |      | Only for 378-409 Ride height      |
| 13   | S-21251   | Air Spring Mounting Kit     | 1.00 |      | Only for 350-381 Ride height      |
| 12   | 98948-001 | Plate-Air Spring Mounting   | 2.00 |      |                                   |
| 11   | S-21208   | Air Spring                  | 2.00 |      |                                   |
| 10   | A-21140   | U-Bolt/Spacer Kit           | 1.00 |      |                                   |
| 9    | C-20023   | Upper Shock Clevis          | 2.00 |      | Can be mounted in either position |
| 8    | S-27615   | Shock Bolt Kit              | 1.00 |      | Can be mounted in either position |
| 7    | S-21699   | Shock absorber              | 2.00 |      | Can be mounted in either position |
| 6    | S-24691   | Tri-Function Bush Kit       | 2.00 |      |                                   |
| 5    | S-24680   | Pivot Bolt/Washer Kit, QA   | 2.00 |      |                                   |
| 4    | D-21179-2 | Frame Bracket assembly (RH) | 1.00 |      |                                   |
| 3    | D-21179-1 | Frame Bracket assembly (LH) | 1.00 |      |                                   |
| 2    | S-27614-2 | Beam Assembly (RH)          | 1.00 |      |                                   |
| 1    | S-27614-1 | Beam Assembly (LH)          | 1.00 |      |                                   |
| Item | Part No   | Description                 | Qty  | Unit | Notes                             |